

**Dhr. Chris Heynen**  
**HEYNEN SYSTEMS BV**  
**Staalstraat 31**  
**NL-8211 AH LELYSTAD**  
**NEDERLAND**

**your delivery of**  
2008-05-29

**your reference**

**our reference**  
PVH/10721

**date**  
Zwijnaarde, 2008-11-24

## **Analysis Report 63346/O**

Required tests :

### **Determination of the abrasion resistance of a woven fabric - Martindale**

Identification number	Information given by the client	Date of receipt
T805814	Circular knitting, 100% polyamide yarn, 110dtex, rib	2008-06-02

Pros Van Hoeyland  
order responsible

For further information, please contact our sectorial adviser Pros Van Hoeyland

This report runs to 2 pages and may be reproduced, as long as it is presented in its entire form, without written permission of Centexbel. The results of the analysis cover the received samples. Centexbel is not responsible for the representativeness of the samples.

Reference : T805814 - Circular knitting, 100%polyamide yarn, 110dtex, rib

Determination of the abrasion resistance of a woven fabric - Martindale

**1. Method:**

Applied standard : EN ISO 12947 part 2 (year: 1998)  
on conditioned material (20°C and 65% rel. hum.)

Deviations of the standard : - between the tested sample and the PUR foam was the  
reference abradant placed.  
- the sample is (slightly) stretched for fixing into the holder

Apparatus : Martindale Abrasion Machine

Pressure on test specimen : 12 kPa

Reference abradant : crossbred worsted spun, plain woven fabric

Type of the felt : woven felt

Number of test specimens : 4 circular test specimens to the end point

**2. Results:**

Date of ending the test: 21-11-2008

Physically significant end point: a hole into the knitting

specimen	number of rubs at which specimen breakdown occurs
1	>100 000
2	>100 000
3	>100 000
4	>100 000
mean	>100 000

See test specimens enclosed.